

**To:** Wagner, Christine[Wagner.Christine@epa.gov]; [Nonresponsive Based on revised scope]@erllc.com]; [Nonresponsive Based on revised scope]@westonsolutions.com]  
**Cc:** [Nonresponsive Based on revised scope]@WestonSolutions.com]; McCauley, Joanna[McCauley.Joanna@epa.gov]; [Nonresponsive Based on revised scope]@westonsolutions.com]  
**From:** [Nonresponsive Based on revised scope]@WestonSolutions.com]  
**Sent:** Thur 11/21/2019 9:35:26 PM (UTC)  
**Subject:** Shiloh - Conex Box Survey 11/8/19  
[Conex Survey 191108.pdf](#)

Attached is survey of the radiological storage area conducted two weeks ago on 11/8/19. The highest exterior reading was outside Rad Storage-2 of 314 µR/hour. The front of the conex towards any workers is all below 100 µR/hour.  
If you have any questions, please let me know.  
Thanks.  
Erik

[Nonresponsive Based on revised scope]  
Region III START  
**Weston Solutions, Inc.**  
[Nonresponsive Based on revised scope]  
[Nonresponsive Based on revised scope]@westonsolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.